

RECEIVED

JUL 17 1991

STATE OF UTAH  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING  
355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
Telephone: (801) 538-5340  
Fax: (801) 359-3940

DIVISION OF  
OIL GAS & MINING

DOGM  
MINERALS PROGRAM  
FILE COPY

### ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

#### I. GENERAL INFORMATION

1. Report Time Period: From (mo./yr.) 1/90 To (mo./yr.) 12/90

S 053 008 SOUTH

2. DOGM File Number: S 1053/015 NORTH

3. Mine Name: Shivwits

4. Mineral(s) Mined: Gypsum

5. Legal Description (Location of Lands Affected):

S/053/008 SW 1/4, NE 1/4, Section 14, Township 41S, Range 18W SOUTH  
\_\_\_\_ 1/4, \_\_\_\_ 1/4, Section \_\_\_\_\_, Township \_\_\_\_\_, Range \_\_\_\_\_

S/053/015 NW 1/4, SE 1/4, NW 1/4, Section 4, Township 41S, Range 18W NORTH

6. Name of Operator or Company: Lanny L. Jensen

7. Permanent Address: P.O. Bx 416 Richfield UT. 84701  
801-896-5956

8. Company Representative (~~or designated operator~~): Owner.

Name: JOHN E. WELSH

Title: Owner of Claims

Address: 4780 Bonair St Holladay ut. 84117

Phone: 801-278-6657

- ☐ Please check if any of the above information has changed since previous year.

## II. MINING AND RECLAMATION

1. Was the mine active during the past year? Yes ☐ No ☒

2. If active, how much ore or mineral was mined? NONE

3. How much new or additional acreage was affected during past year? NONE

4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.

1990 No new surface area disturbed - Assessment  
Activities on previously disturbed areas.

1991 Activities planned in July, August 1991

5. How much acreage was reclaimed during past year? NONE

6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

7. What is the total disturbed acreage at years end? greater than 771  
> 5 acres > 5 acres each locality

8. Briefly summarize mining and reclamation planned for the upcoming year.

Reclaim older access route into N. Shirwitz claims

NOTE: Section III., "Additional Information" applies only to large mining operations.

### III. ADDITIONAL INFORMATION

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

### IV. SIGNATURE REQUIREMENT

I hereby certify that the foregoing is true and correct.

Name (Typed or Print): Larry L. Jensen

Title of Operator: Operator under Mining Agreement 0347889  
BK 0520  
Pg. 0782  
WA CO.

Signature of Operator: Larry L. Jensen  
by John E. Hetch

Date: 15 July 1991

jb  
MR-AR